# HYUNDAI ELANTRA 2024

| 1 FRONT BUMPER | 2 GRILLE BK W/SENSOR HOLE | 3 FOG LAMP COVER W/HOLE |
|---|---|---|
| | | |

| 4 FRONT BUMPER BRACKET | 5 REAR BUMPER BRACKETT | 6 FRONT INNER FENDER |
|---|---|---|
| | | |

| NO | CODE | DESCRIPTION | | MODEL | YEAR | OEM | PCS | NW | GW | M3 | PART LINK |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | HYB223 NA | FRONT BUMPER | | ELANTRA | 2024-2025 | 86510-AABA0 | 1 | 3.95 | 4.25 | 0.0600 | |
| 2 | HYG223 NA | GRILLE BK W/SENSOR HOLE | | ELANTRA | 2024-2025 | 86350-AABB0PKB | 5 | 5.72 | 6.50 | 0.0600 | |
| 3 | HYFC223 LB | FOG LAMP COVER W/HOLE LH | | ELANTRA | 2024-2025 | 86563-AAAB0 | 1 | 0.12 | 0.12 | 0.0005 | |
| | HYFC223 RB | FOG LAMP COVER W/HOLE RH | | ELANTRA | 2024-2025 | 86564-AAAB0 | 1 | 0.12 | 0.12 | 0.0005 | |
| 4 | HYBS223 LA | FRONT BUMPER BRACKET LH | | ELANTRA | 2024-2025 | 86551-AAAA0 | 1 | 0.03 | 0.03 | 0.0002 | |
| | HYBS223 RA | FRONT BUMPER BRACKET RH | | ELANTRA | 2024-2025 | 86552-AAAA0 | 1 | 0.03 | 0.03 | 0.0005 | |
| 5 | HYBS224 LA | REAR BUMPER BRACKETT LH | LA | ELANTRA | 2024-2025 | 86651-AAAA0 | 1 | 0.19 | 0.19 | 0.0050 | |
| | HYBS224 RA | REAR BUMPER BRACKET RH | RA | ELANTRA | 2024-2025 | 86652-AAAA0 | 1 | 0.19 | 0.19 | 0.0050 | |
| 6 | HYIF223 LA | FRONT INNER FENDER LH | | ELANTRA | 2024-2025 | 86511-AAAA0 | 10 | 9.45 | 9.45 | 0.0400 | |
| | HYIF223 RA | FRONT INNER FENDER RH | | ELANTRA | 2024-2025 | 86812-AAAA0 | 10 | 9.45 | 9.45 | 0.0400 | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |