# TOYOTA CORONA ALLION NZT260 2010-2016

**1 FRONT BUMPER**

**2 REAR BUMPER**

**3 GRILLE CP/BK**

**4 HEAD LAMP CLEAR**

**5 HEAD LAMP BLACK**

**6 FOG LAMP**

**7 FOG LAMP COVER W/O HOLE**

**8 FOG LAMP COVER WITH HOLE**

**9 TAIL LAMP**

**10 FRONT INNER FENDER**

**11 BUMPER MOULDING LOWER**

**12 FRONT BUMPER BRACKET**

| NO | CODE | DESCRIPTION | MODEL | YEAR | OEM | PCS | NW | GW | M3 | PART LINK |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | TYB265 NA | FRONT BUMPER | ALLION NZT260 | '10-'16 | 52119-20B20/30 | 1 | 3.28 | 3.65 | 0.0600 | |
| 2 | TYB264 NA | REAR BUMPER | ALLION NZT260 | '07-'11 | 52159-20A20-A0 | 1 | 3.31 | 3.69 | 0.0600 | |
| | TYB264 NW | REAR BUMPER WHITE 040 | ALLION NZT260 | '07-'11 | 52159-20A20-A0 | 1 | 4.00 | 4.38 | 0.0600 | |
| 3 | TYG265 NA | GRILLE CP/BK | ALLION NZT260 | '11-'12 | 53111-20B30 | 1 | 2.00 | 2.00 | 0.0300 | |
| 4 | TYHL265 LA | HEAD LAMP CLEAR LH | ALLION | '10 | 81170-20B20 | 1 | 2.00 | 2.63 | 0.0377 | |
| | TYHL265 RA | HEAD LAMP CLEAR RH | ALLION | '10 | 81130-20B20 | 1 | 2.00 | 2.63 | 0.0377 | |
| 5 | TYHL265 LB | HEAD LAMP BLACK LH | ALLION | '10 | 81170-20B21 | 1 | 2.00 | 2.63 | 0.0377 | |
| | TYHL265 RB | HEAD LAMP BLACK RH | ALLION | '10 | 81130-20B21 | 1 | 2.00 | 2.63 | 0.0377 | |
| 6 | TYFL265 LA | FOG LAMP LH | CORONA ALLION | '11 | 81220-0D041 | 1 | | | | |
| | TYFL265 RA | FOG LAMP RH | CORONA ALLION | '11 | 81210-0D041 | 1 | | | | |
| 7 | TYFC265 LA | FOG LAMP COVER W/O HOLE LH | ALLION NZT260 | '10-'16 | 52128-20220 | 5 | 0.17 | 1.30 | 0.0200 | |
| | TYFC265 RA | FOG LAMP COVER W/O HOLE RH | ALLION NZT260 | '10-'16 | 52127-20260 | 5 | 0.17 | 1.30 | 0.0200 | |
| 8 | TYFC265 LB | FOG LAMP COVER WITH HOLE LH | ALLION NZT260 | '10-'16 | 52128-20150 | 5 | 0.17 | 1.30 | 0.0200 | |
| | TYFC265 RB | FOG LAMP COVER WITH HOLE RH | ALLION NZT260 | '10-'16 | 52127-20250 | 5 | 0.17 | 1.30 | 0.0200 | |
| 9 | TYL265 LA | TAIL LAMP LH | CORONA ALLION | '10 | 81560/61-20A50 | 1 | 1.10 | 1.63 | 0.0278 | |
| | TYL265 RA | TAIL LAMP RH | CORONA ALLION | '10 | 81550/51-20A50 | 1 | 1.10 | 1.63 | 0.0278 | |
| 10 | TYIF265 LA | FRONT INNER FENDER LH | ALLION/PRIMIO | '10-'14 | 53876-20420 | 10 | 4.00 | 4.00 | 0.0300 | |
| | TYIF265 RA | FRONT INNER FENDER RH | ALLION/PRIMIO | '10-'14 | 53275-20370 | 10 | 4.00 | 4.00 | 0.0300 | |
| 11 | TYBM265 LA | BUMPER MOULDING LOWER LH | CORONA ALLION | '10-'16 | 52542-20020 | 1 | | | | |
| | TYBM265 RA | BUMPER MOULDING LOWER RH | CORONA ALLION | '10-'16 | 52541-20020 | 1 | | | | |
| 12 | TYBS265 LA | FRONT BUMPER BRACKET LH | CORONA ALLION | '10-'16 | 52576-20800 | 1 | | | | |
| | TYBS265 RA | FRONT BUMPER BRACKET RH | CORONA ALLION | '10-'16 | 52575-20800 | 1 | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |