TOYOTA LAND CRUISER 2022

1 FRONT BUMPER 7 IN 1 (VXR)

2 GRILLE CP/SV/BK

3 FRONT BUMPER MOULDING CP

4 REAR BUMPER 2 IN 1

5 RR HOOK HOLE COVER MAT BK

6 FRONT BUMPER BRACKET

7 PLATE REAR BUMPER UPPER

8 REAR BUMPER BRACKET

NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB451 NA	FRONT BUMPER 7 IN 1 (VXR)	LAND CRUISER	'22	76851-60900(B)	1	5.40	6.00	0.0600	
					52119-6C935(UP)					
					53113-60200(BFL)					
					53112-60440(BFR)					
					53112-60470(BF)					
					52711-60120(LW)					
					53111-60C70(IN)					
2	TYG451 NA	GRILLE CP/SV/BK	LAND CRUISER	'22	53101-60G70	5	10.33	12.35	0.3900	
3	TYBM451 NA	FRONT BUMPER MOULDING CP	LAND CRUISER	'22		20	12.00	13.50	0.0400	
4	TYB452 NA	REAR BUMPER 2 IN 1 (VXR)	LAND CRUISER	'22	52159-6A974(UP)	1	6.00	6.50	0.0800	
					52169-60911(LW)					
5	TYB452SP NA	RR HOOK HOLE COVER MAT BK	LAND CRUISER	'22	52151-60220	50	10.00	11.00	0.0600	
6	TYBS451 LA	FRONT BUMPER BRACKET LH	LAND CRUISER	'22	52116-60280	40	8.76	9.89	0.0700	
	TYBS451 RA	FRONT BUMPER BRACKET RH	LAND CRUISER	'22	52115-60280	40	8.76	9.89	0.0700	
7	TYP452 UA	PLATE REAR BUMPER UPPER	LAND CRUISER	'22	52162-60130	1	0.90			
8	TYBS452 LA	REAR BUMPER BRACKET LH	LAND CRUISER	'22	52156-60150	1	0.32			
	TYBS452 RA	REAR BUMPER BRACKET RH	LAND CRUISER	'22	52155-60150	1	0.32			