TOYOTA LAND CRUISER PRADO 2018

1 FRONT BUMPER W/O FINISHER

2 BUMPER FINISHER

3 GRILLE CP/BK

4 GRILLE CP/GYM

5 FRONT BUMPER MOULDING UPPER

6 HEAD LAMP BRACKET

7 REAR BUMPER

8 HEAD LAMP HALOGEN

9 HEAD LAMP LED

10 TAIL LAMP LED

11 HOOD

12 FENDER W/O SIDE LAMP HOLE

NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB277 NA	FRONT BUMPER W/O FINISHER	PRADO	'18	52119-6B979/80/85/86	1	4.05	4.51	0.0600	
2	TYBF277 NA	BUMPER FINISHER	PRADO	'18	53112-60290	10	6.01	6.04	0.1390	
3	TYG277 NA	GRILLE CP/BK	PRADO	'18	53101-60E70/80/90	5	7.41	7.41	0.1331	
4	TYG277 NB	GRILLE CP/GYM	PRADO	'18	53101-60E70/80/90	5	7.42	7.42	0.1300	
5	TYHC277 LA	FRONT BUMPER MOULDING UPPER LH	PRADO	'18	53148-60010	35	7.49	9.49	0.1800	
	TYHC277 RA	FRONT BUMPER MOULDING UPPER RH	PRADO	'18	53147-60020	35	7.49	9.49	0.1800	
6	TYHB277 LA	HEAD LAMP BRACKET LH	PRADO	'18	53246-60020	1	0.28	0.33	0.0224	
	TYHB277 RA	HEAD LAMP BRACKET RH	PRADO	'18	53245-60020	1	0.28	33.00	0.0224	
7	TYB278 NA	REAR BUMPER	PRADO	'18	52159-6A963/64	1	3.72	4.19	0.0600	
8	TYHL277 LA	HEAD LAMP HALOGEN LH	PRADO	'18	81170-60N00	1	4.50	5.00	0.0600	
	TYHL277 RA	HEAD LAMP HALOGEN RH	PRADO	'18	81130-60N00		4.76	5.14		
9	TYHL277 LB	HEAD LAMP LED LH	PRADO	'18	81185-60N20		6.61	7.14		
	TYHL277 RB	HEAD LAMP LED RH	PRADO	'18	81185-60N20		6.61	7.14		
10	TYL277 LA	TAIL LAMP LED LH	PRADO	'18	81561-60C30	1	1.86	2.55	0.0366	
	TYL277 RA	TAIL LAMP LED RH	PRADO	'18	81551-60C30	1	1.86	2.55	0.0366	
11	TYH277 NA	HOOD	PRADO	'18	53301-60760	1	14.00	16.00	0.1500	
12	TYF277 LA	FENDER W/O SIDE LAMP HOLE LH	PRADO	'18	53802-60E10	1	5.00	5.50	0.0650	
	TYF277 RA	FENDER W/O SIDE LAMP HOLE RH	PRADO	'18	53801-60E10	1	5.00	5.50	0.0650	

TOYOTA LAND CRUISER PRADO 2018

1 DOOR MOULDING 4PCS/SET

2 FRONT BUMPER BRACKET

3 INNER FENDER

NO	CODE	DESCRIPTION		MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYDT277 SA	DOOR MOULDING 4PCS/SET	F.RH	PRADO	'18	PZ329-60073/77(RH)					
			F.LH	PRADO	'18	PZ329-60074/78(LH)					
			R.RH	PRADO	'18	PZ329-60075/79(RH)					
			R.LH	PRADO	'18	PZ329-60076/80(LH)					
2	TYBS277 LA	FRONT BUMPER BRACKET LH		PRADO	'18	52116-60270	100	7.00	8.45	0.0909	
	TYBS277 RA	FRONT BUMPER BRACKET RH		PRADO	'18	52115-60220	100	7.00	8.45	0.0909	
3	TYIF277 LA	INNER FENDER LH		PRADO	'18	53806-60120	25	18.21	18.21	0.0800	
	TYIF277 RA	INNER FENDER RH		PRADO	'18	53805-60120	25	18.21	18.21	0.0800	