# TOYOTA YARIS 2022 ATIV SEDAN

**1 FR BUMPER W/FINISHER**

**2 HOOK HOLE COVER**

**3 GRILLE BASE BK**



**4 GRILLE MOULDING**

**5 REAR BUMPER WITH LOWER PANEL**

**6 FOG LAMP COVER**

**7 FRONT BUMPER BRACKET**



**8 FRONT INNER FENDER**

**9 REAR BUMPER BRACKET**

**10 REAR MOULDING COVER**

**11 REAR BUMPER REFLECTOR**

| NO | CODE | DESCRIPTION | MODEL | YEAR | OEM | PCS | NW | GW | M3 | PART LINK |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | TYB481 NA | FR BUMPER W/FINISHER | YARIS ATIV | '22-'23 | 52119-BZ911(B) | 1 | 5.00 | 5.50 | 0.0600 | |
| | | | | | 53112-BZ320-C0(BF) | | | | | |
| 2 | TYB481SP NA | HOOK HOLE COVER | YARIS ATIV | '22-'23 | 52721-BZ120-C0 | 1 | 0.15 | 0.15 | 0.0050 | |
| 3 | TYG481 NA | GRILLE BASE BK | YARIS ATIV | '22-'23 | 53114-BZ010 | 5 | 1.50 | 2.00 | 0.0200 | |
| 4 | TYGM481 NA | GRILLE MOULDING | YARIS ATIV | '22-'23 | 53111-BZ666-C0 | 5 | 2.00 | 2.50 | 0.0200 | |
| 5 | TYB482 NA | REAR BUMPER WITH LOWER PANEL | YARIS ATIV | '22-'23 | 52159-BZ901(B) | 1 | 4.50 | 4.80 | 0.0600 | |
| | | | | | 52169-BZ140(P) | | | | | |
| 6 | TYFC481 LA | FOG LAMP COVER LH | YARIS ATIV | '22-'23 | 52128-BZ420-C0 | 5 | 1.50 | 2.00 | 0.0200 | |
| | TYFC481 RA | FOG LMAP COVER RH | YARIS ATIV | '22-'23 | 52127-BZ460-C0 | 5 | 1.50 | 2.00 | 0.0200 | |
| 7 | TYBS481 LA | FRONT BUMPER BRACKET LH | YARIS ATIV | '22-'23 | 52536-BZ010 | 1 | 0.15 | 0.15 | 0.0050 | |
| | TYBS481 RA | FRONT BUMPER BRACKET RH | YARIS ATIV | '22-'23 | 52535-BZ010 | 5 | 1.50 | 2.00 | 0.0200 | |
| 8 | TYIF481 LA | FRONT INNER FENDER LH | YARIS ATIV | '22-'23 | 53806-BZ120 | 10 | 10.00 | 11.00 | 0.0600 | |
| | TYIF481 RA | FRONT INNER FENDER RH | YARIS ATIV | '22-'23 | 53805-BZ120 | 10 | 10.00 | 11.00 | 0.0600 | |
| 9 | TYBS482 LA | REAR BUMPER BRACKET LH | YARIS ATIV | '22-'23 | 52576-BZ010 | 1 | 0.35 | 0.35 | 0.0010 | |
| | TYBS482 RA | REAR BUMPER BRACKET RH | YARIS ATIV | '22-'23 | 52575-BZ010 | 1 | 0.35 | 0.35 | 0.0010 | |
| 10 | TYFC482 LA | REAR MOULDING COVER LH | YARIS ATIV | '22-'23 | 52573-BZ160-B0 | 1 | 0.35 | 0.35 | 0.0200 | |
| | TYFC482 RA | REAR MOULDING COVER RH | YARIS ATIV | '22-'23 | 52752-BZ160-B0 | 1 | 0.35 | 0.35 | 0.0200 | |
| 11 | TYBL482 LA | REAR BUMPER REFLECTOR LH | YARIS ATIV | '22-'23 | 81920-BZ300 | 50 | 7.00 | 7.50 | 0.0200 | |
| | TYBL482 RA | REAR BUMPER REFLECTOR RH | YARIS ATIV | '22-'23 | 81910-BZ300 | 50 | 7.00 | 7.50 | 0.0200 | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

# TOYOTA YARIS 2022 ATIV SEDAN

**1 FENDER W/O SIDE LAMP HOLE**

**2 FENDER W/SIDE LAMP HOLE**



**3 HOOD**

**4 HEAD LAMP**

**5 HEAD LAMP LED**

**6 TAIL LAMP HALOGEN**

**7 TAIL LAMP W/ONE LED**

**8 TAIL GATE/TRUNK LID**

| NO | CODE | DESCRIPTION | MODEL | YEAR | OEM | PCS | NW | GW | M3 | PART LINK |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | TYF481 LA | FENDER W/O SIDE LAMP HOLE LH | YARIS SEDAN | '22 | 53812-BZ620 | 1 | 5.00 | 6.00 | 0.0300 | |
| | TYF481 RA | FENDER W/O SIDEN LAMP RH | YARIS SEDAN | '22 | 53811-BZ620 | 1 | 5.00 | 6.00 | 0.0300 | |
| 2 | TYF481 LB | FENDER W/SIDE LAMP HOLE LH | YARIS SEDAN | '22 | 53812-BZ640 | 1 | 5.00 | 6.00 | 0.0300 | |
| | TYF481 RB | FENDER W/SIDE LAMP HOLE RH | YARIS SEDAN | '22 | 53811-BZ640 | 1 | 5.00 | 6.00 | 0.0300 | |
| 3 | TYH481 NA | HOOD | YARIS SEDAN | '22 | 53301-BZ430 | 1 | 15.00 | 16.00 | 0.0600 | |
| 4 | TYHL481 LA | HEAD LAMP LH | YARIS SEDAN | '22 | 81150-BZB30 | 1 | 8.00 | 9.00 | 0.0200 | |
| | TYHL481 RA | HEAD LAMP RH | YARIS SEDAN | '22 | 81110-BZB30 | 1 | 8.00 | 9.00 | 0.0200 | |
| 5 | TYHL481 LB | HEAD LAMP LED LH | YARIS SEDAN | '22 | 81150-BZ860(SA) | 1 | 8.00 | 9.00 | 0.0200 | |
| | TYHL481 RB | HEAD LAMP LED RH | YARIS SEDAN | '22 | 81110-BZ860(SA) | 1 | 8.00 | 9.00 | 0.0200 | |
| 6 | TYL481 LA | TAIL LAMP HALOGEN LH | YARIS SEDAN | '22 | 81560-BZ640 | 10 | 11.00 | 12.00 | 0.0400 | |
| | TYL481 RA | TAIL LAMP HALOGEN RH | YARIS SEDAN | '22 | 81550-BZ640 | 10 | 11.00 | 12.00 | 0.0400 | |
| 7 | TYL481 LB | TAIL LAMP W/ONE LED LH | YARIS SEDAN | '22 | 81560-BZ620 | 10 | 11.00 | 12.00 | 0.0400 | |
| | TYL481 RB | TAIL LAMP W/ONE LED RH | YARIS SEDAN | '22 | 81550-BZ620 | 10 | 11.00 | 12.00 | 0.0400 | |
| 8 | TYT481 NA | TAIL GATE/TRUNK LID | YARIS SEDAN | '22 | 64401-BZ090 | 1 | 11.00 | 12.00 | 0.0400 | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |