TOYOTA FJ CRUISER 2007-2010

1 FRONT BUMPER W/ BUMPER FINISHER

2 SIDE BUMPER

3 GRILLE CP/BK

4 GRILLE SV/BK

5 GRILLE MAT BK

6 HEAD LAMP

7 CORNER LAMP AMBER

8 TAIL LAMP

9 FRONT FENDER BRACKET SIDE

NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB391 NA	FRONT BUMPER W/ BUMPER FINISHER	FJ CRUISER	'03-'15	52119-35071/53112-35030(BF)	1	3.07	3.37	0.0600	
2	TYS391 LA	SIDE BUMPER MAT BK LH	FJ CRUISER	'03-'15	52423-35020	1	0.39	1.52	0.0100	
	TYS391 RA	SIDE BUMPER MAT BK RH	FJ CRUISER	'03-'15	52422-35030	1	0.38	1.51	0.0100	
3	TYG391 NA	GRILLE CP/BK	FJ CRUISER	'03-'15	53100-35A30	5	6.52	8.49	0.1533	
4	TYG391 NB	GRILLE SV/BK	FJ CRUISER	'03-'15	53100-35A31	5	6.52	8.49	0.1533	
5	TYG391 NE	GRILLE MAT BK	FJ CRUISER	'03-'15	53100-35A31	5	6.58	8.54	0.1533	
6	TYHL391 LA	HEAD LAMP LH	FJ CRUISER	'07-'15	81070-35511	1	1.47	1.59		
	TYHL391 RA	HEAD LAMP RH	FJ CRUISER	'07-'15	81140-35511	1	2.35	2.54		
7	TYCL391 LA	CORNER LAMP AMBER LH	FJ CRUISER	'07-'15	81171-35550	1	0.87	0.94		
	TYCL391 RA	CORNER LAMP AMBER RH	FJ CRUISER	'07-'15	81131-35560	1	0.96	1.04		
8	TYL391 LA	TAIL LAMP LH	FJ CRUISER	'07-'15	81551-35341	1	1.43	1.54	0.0300	
	TYL391 RA	TAIL LAMP RH	FJ CRUISER	'07-'15	81561-35301	1	1.42	1.53	0.0300	
9	TYFB391 LA	FRONT FENDER BRACKET SIDE LH STEEL	FJ CRUISER	'07-'15	61102-35132	1	0.50	0.50	0.0050	
	TYFB391 RA	FRONT FENDER BRACKET SIDE RH STEEL	FJ CRUISER	'07-'15	61101-35172	1	0.50	0.50	0.0050	