TOYOTA YARIS ATIV / HATCH BACK 2020-2022

1 FRONT BUMPER WITH FINISHER (4 IN 1)

2 GRILLE BASE MAT BK

3 GRILLE MOULDING ROUND CENTER BK

4 GRILLE MOULDING BK

5 GRILLE MOULDING CP

6 FRONT BUMPER BRACKET

7 FOG LAMP COVER W/O HOLE

8 FOG LAMP COVER W/HOLE

9 WASHER TANK

10 SEAL RR BUMPER SIDE

11 R.BUMPER BRACKET SEDAN

NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB217 NA	FRONT BUMPER WITH FINISHER (4 IN 1)	YARIS SEDAN	'20-'22	52119-YP913	1	3.51	3.93	0.0600	
2	TYG217 NA	GRILLE BASE MAT BK	YARIS	'20-'22	53114-YP090	5	2.04	3.37	0.0900	
					53101-YP170/180/190					
3	TYGM217 CA	GRILLE MOULDING ROUND CENTER BK	YARIS	'20-'22	53111-YP907(SA)	30	4.20	5.33	0.0700	
4	TYGM217 LA	GRILLE MOULDING LH BK	YARIS	'20-'22	52314-YP200	1,000	17.00	18.13	0.0700	
	TYGM217 RA	GRILLE MOULDING RH BK	YARIS	'20-'22	53123-YP200	1,000	17.00	18.13	0.0700	
5	TYGM217 LB	GRILLE MOULDING LH CP	YARIS	'20-'22	53124-YP220	1,000	17.00	18.13	0.0700	
	TYGM217 RB	GRILLE MOULDING RH CP	YARIS	'20-'22	53123-YP220	1,000	17.00	18.13	0.0700	
6	TYBS215 LA	FRONT BUMPER BRACKET LH	YARIS	'18-'22	52536-0D230	50	5.41	6.53	0.0695	
	TYBS215 RA	FRONT BUMPER BRACKET RH	YARIS	'18-'22	52535-0D230	50	5.41	6.54	0.0695	
7	TYFC217 LA	FOG LAMP COVER W/O HOLE LH	YARIS	'20-'22	52128-YP360(SA)	40	4.04	5.17	0.0700	
	TYFC217 RA	FOG LAMP COVER W/O HOLE RH	YARIS	'20-'22	52127-YP360(SA)	40	4.04	5.17	0.0700	
8	TYFC217 LB	FOG LAMP COVER W/HOLE LH	YARIS	'20-'22	52128-YP280(LH)	1	0.09	0.09	0.0100	
	TYFC217 RB	FOG LAMP COVER W/HOLE RH	YARIS	'20-'22	52127-YP280(TH)	1	0.09	0.09	0.0100	
9	TYWW217 NA	WINDSCREEN WASHER TANK	YARIS	'20-'22		1	0.25			
10	52591-0D460	SEAL RR BUMPER SIDE RH SEDAN	YARIS ATIV	'16-'22	52591-0D460	1				
	52592-0D460	SEAL RR BUMPER SIDE LH SEDAN	YARIS ATIV	'16-'22	52592-0D460	1				
11	TYBS216 LA	R.BUMPER BRACKET SEDAN/4 DOOR LH	YARIS ATIV	'18-'19	52576-0D330	30	5.42	6.55	0.0752	
	TYBS216 RA	R.BUMPER BRACKET SEDAN/4 DOOR RH	YARIS ATIV	'18-'19	52575-0D340	30	5.42	6.55	0.0752	