

MITSUBISHI PAJERO / MONTERO 1992-1993



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	MBG030 NA	GRILLE CP/ARG	PAJERO V31	'92-'96	MB831060/MB070003GA	5	7.00	9.00	0.1380	
2	MBG030 NB	GRILLE BK	PAJERO V31	'92-'96	MB831059/MB07003GB	5	7.00	9.00	0.1380	
3	MBG030 NC	GRILLE ALL CP	PAJERO V31	'92-'96	MB831059	5	7.00	9.00	0.1380	
4	MBHL030 LA	HEAD LAMP LH NORMAL	PAJERO V32	'92-'94	MB831067	6	8.00	10.00	0.1160	
	MBHL030 RA	HEAD LAMP RH NORMAL	PAJERO V32	'92-'94	MB831068	6	8.00	10.00	0.1160	
5	MBCL030 LA	CORNER LAMP AMBER/CLEAR LH	PAJERO V32	'92-'94	MB831079	20	8.00	11.40	0.1000	
	MBCL030 RA	CORNER LAMP AMBER/CLEAR RH	PAJERO V32	'92-'94	MB831080	20	8.00	11.40	0.1440	
6	MBCL030 LB	CORNER LAMP LH ALL CLEAR	PAJERO V32	'92-'94	MB831079	20	5.00	6.00	0.1440	
	MBCL030 RB	CORNER LAMP RH ALL CLEAR	PAJERO V32	'92-'94	MB831080	20	5.00	6.00	0.1440	
7	MBCL030 LC	CORNER LAMP AMBER/CRYSTAL LH	PAJERO V32	'92-'94	MB831081	20	5.00	6.00	0.1440	
	MBCL030 RC	CORNER LAMP AMBER/CRYSTAL RH	PAJERO V32	'92-'94	MB831082	20	5.00	6.00	0.1440	
8	MBSL030 NA	SIDE LAMP	PAJERO V32	'92-'94	MB831091	200	12.00	14.00	0.0704	
9	MBL030 LA	TAIL LAMP LH CP	PAJERO V32	'92-'96	MB831489	10	6.80	7.20	0.0984	
	MBL030 RA	TAIL LAMP RH CP	PAJERO V32	'92-'96	MB831490	10	6.50	7.20	0.0984	
10	MBL030 LB	TAIL LMAP LH BK	PAJERO V32	'92-'94	MB831085	20	8.00	10.00	0.1100	
	MBL030 RB	TAIL LAMP RH BK	PAJERO V32	'92-'94	MB831086	20	8.00	10.00	0.1100	
11	MBL030 LC	TAIL LAMP LH CP CRYSTAL	PAJERO V32	'92-'94	MB831489	20	8.00	10.00	0.1100	
	MBL030 RC	TAIL LAMP RH CP CRYSTAL	PAJERO V32	'92-'94	MB831490	20	8.00	10.00	0.1100	
12	MBL030 LD	TAIL LAMP BLACK/CLEAR/RED LH	PAJERO V31	'92-'96		1				
	MBL030 RD	TAIL LAMP BLACK/CLEAR/RED RH	PAJERO V31	'92-'96		1				
13	MBS029 LA	SIDE BUMPER LH SHORT BK	PAJERO V32	'92-'94	MB831049	5	5.00	6.00	0.0500	
	MBS029 RA	SIDE BUMPER RH SHORT BK	PAJERO V32	'92-'94	MB831050	5	5.00	6.00	0.0500	
14	MBS030 LA	F. SIDE BUMPER LH W/ NOZZLE HOLE	PAJERO V32	'92-'96	MB831047	5	6.00	8.00	0.0600	
	MBS030 RA	F. SIDE BUMPER RH W/ NOZZLE HOLE	PAJERO V32	'92-'96	MB831048	5	6.00	8.00	0.0600	
15	MBS030 LB	SIDE BUMPER LH W/O NOZZLE HOLE	PAJERO V32	'92-'94	MB679541	5	5.00	6.00	0.0600	
	MBS030 RB	SIDE BUMPER RH W/O NOZZLE HOLE	PAJERO V32	'92-'94	MB679542	5	5.00	6.00	0.0600	

