

## MITSUBISHI PAJERO 2001-2003 (V73)



**1 FRONT BUMPER W/O WASHER HOLE**



**2 FRT BUMPER PRIMED BK**



**3 REAR BUMPER**



**4 REAR SIDE BUMPER**



**5 REAR SIDE BUMPER  
W/ NARROW HOLE FOR LEBANON**



**6 GRILLE SV**



**7 GRILLE BK**



**8 GRILLE CP/BK**



**9 GRILLE ALL CP**



**10 FOG LAMP COVER**



**11 FOG LAMP**



**12 REAR BACK LAMP**



**13 TAIL LAMP WT ( 3CONNECTORS )**



**14 TAIL LAMP CP (3CONNECTORS)**



**15 FRONT MUD GUARD**



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	MBB059 NA	FRONT BUMPER W/O WASHER HOLE	PAJERO V78	'01-'03	MR508248/246	1	3.01	3.39	0.0600	
2	MBB059 NC	FRT BUMPER PRIMED BK	MONTERO 2800CC	'01-'03	MR508248	1	3.17	3.55	0.0600	
3	MBIB060 NA	REAR BUMPER	PAJERO	'01	MR533016	1	4.50	5.00	0.0600	
4	MBS060 LA	REAR SIDE BUMPER LH	PAJERO	'01-'03	MR548827	5	8.10	11.50	0.3000	
	MBS060 RA	REAR SIDE BUMPER RH	PAJERO	'01-'03	MR548828	5	1.60	2.80	0.3000	
5	MBS060 LB	REAR SIDE BUMPER LH W/ NARROW HOLE FOR LEBANON	PAJERO	'01-'03	MR508177	5	1.60	2.08	0.3000	
	MBS060 RB	REAR SIDE BUMPER RH W/ NARROW HOLE FOR LEBANON	PAJERO	'01-'03	MR508178	5	160.00	2.08	0.3000	
6	MBG059 NA	GRILLE SV	PAJERO	'01-'03	MR441863	1	1.18	2.21	0.0500	
7	MBG059 NB	GRILLE BK	PAJERO	'01-'03	MR387982	1	1.18	2.21	0.0492	
8	MBG059 NC	GRILLE CP/BK	PAJERO	'01-'03	MR387981	1	1.50	1.50	0.0500	
9	MBG059 ND	GRILLE ALL CP	PAJERO	'01-'03	MR387981	1	1.50	1.50	0.0500	
10	MBFC059 LA	FOG LAMP COVER LH	PAJERO V73	'01	MR388019	50	2.00	3.35	0.0300	
	MBFC059 RA	FOG LAMP COVER RH	PAJERO V73	'01	MR388020	50	2.00	3.35	0.0300	
11	MBFL059 LA	FOG LAMP LH	PAJERO V73	'01-'03	MR508189	20	19.00	20.50	0.1006	
	MBFL059 RA	FOG LAMP RH	PAJERO V73	'01-'03	MR508190	20	19.00	20.50	0.1006	
12	MBBL059 LA	REAR BACK LAMP LH	PAJERO	'01-'03	MR508783	40	20.00	22.00	0.1800	
	MBBL059 RA	REAR BACK LAMP RH	PAJERO	'01-'03	MR508784	40	20.00	22.00	0.1800	
13	MBL059 LA	TAIL LAMP LH WT ( 3CONNECTORS )	PAJERO V73	'01-'03	MR508501	10	15.00	17.00	0.2683	
	MBL059 RA	TAIL LAMP RH WT ( 3 CONNECTORS)	PAJERO V73	'01-'03	MR508504	10	15.00	17.00	0.2683	
14	MBL059 LB	TAIL LAMP LH CP (3CONNECTORS)	PAJERO V73	'01-'03	MR508783	10	15.00	17.00	0.2683	
	MBL059 RB	TAIL LAMP RH CP (3CONNECTORS)	PAJERO V73	'01-'03	MR508784	10	15.00	17.00	0.2683	
15	MBMG059 F LA	FRONT MUD GUARD LH	PAJERO V73	'01	MN117279	1	0.64	0.64	0.1815	
	MBMG059 F RA	FRONT MUD GUARD RH	PAJERO V73	'01	MN117280	1	0.64	0.64	0.1815	

