

TOYOTA CORONA ST210 / CARINA / CALDINA 1992-1997



1 F. BUMPER W/O HOLE

2 F.BUMPER W/HOLE

3 FRONT BUMPER W/O FOG LAMP HOLE



4 REAR BUMPER STATION WAGON

5 GRILLE MAT BK

6 HEAD LAMP



7 HEAD LAMP EUROPEAN(FT)

8 CORNER LAMP

9 CORNER LAMP EUROPEAN (FT)



10 INNER FENDER

11 HOOD

12



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB019 NA	F. BUMPER W/O HOLE	CORONA AT191	'93-'97	52119-2B110	1	4.40	4.40	0.0600	
2	TYB019 NB	F.BUMPER W/HOLE	CORONA AT191	'93-'97	52119-2B020	1	4.40	4.40	0.0600	
3	TYB019 NC	FRONT BUMPER W/O FOG LAMP HOLE	CARDINA	'92-'97	52119-2B040	1	4.33	4.50	0.0600	
4	TYB020 NA	REAR BUMPER STATION WAGON	CARDINA	'92-'97	52159-21010	1	4.00	4.00	0.0600	
5	TYG019 NC	GRILLE MAT BK	CARDINA	'96-'00	53101-21010	5	2.41	3.17	0.0344	
6	TYHL019 LA	HEAD LAMP LH	CORONA AT191	'92-'96	81150-2B680	8	2.58	2.79	0.1404	
	TYHL019 RA	HEAD LAMP RH	CORONA AT191	'92-'96	81110-2B680	8	2.65	2.86	0.1404	
7	TYHL019 LC	HEAD LAMP LH EUROPEAN(FT)	CARDINA	'96-'00	81150-2B680	8	7.00	9.00	0.1404	
	TYHL019 RC	HEAD LAMP RH EUROPEAN(FT)	CARDINA	'96-'00	81110-2B680	8	7.00	9.00	0.1404	
8	TYCL019 LA	CORNER LAMP LH	CORONA AT191	'92-'96	81620-20530	40	6.00	8.00	0.2016	
	TYCL019 RA	CORNER LAMP RH	CORONA AT191	'92-'96	81610-20530	40	6.00	8.00	0.2016	
9	TYCL019 LC	CORNER LAMP LH EUROPEAN (FT)	CARDINA	'96-'00	81520-20650	20	8.00	10.00	0.1000	
	TYCL019 RC	CORNER LAMP RH EUROPEAN (FT)	CARDINA	'96-'00	81510-20660	20	8.00	10.00	0.1000	
10	TYIF019 LA	INNER FENDER LH	CORONA AT190	'95	53876-20250-1	1				
	TYIF019 RA	INNER FENDER RH	CORONA AT190	'95	53875-20240-1	1				
11	TYH019 NA	HOOD	CORONA	'92-'97		1				