

TOYOTA CORONA AT181 1990-1992 / CORONA AT19 1995- 1996



1 F. BUMPER W/O HOLE

2 F.BUMPER W/HOLE

3 FRONT BUMPER W/O FOG LAMP HOLE



4 GRILLE GYM '95

5 GRILLE CP/BK '95

6 GRILLE CP



7 GRILLE CP/GYM

8 CORNER LAMP

9 FRONT LAMP



10 SPOTLIGHT COVER

11 INNER FENDER

12 ENGINE UNDER COVER



13 HOOD MOULDING CP/GYM '90-'92



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB019 NA	F. BUMPER W/O HOLE	CORONA AT191	'93-'97	52119-2B110	1	4.40	4.40	0.0600	
2	TYB019 NB	F.BUMPER W/HOLE	CORONA AT191	'93-'97	52119-2B020	1	4.40	4.40	0.0600	
3	TYB019 NC	FRONT BUMPER W/O FOG LAMP HOLE	CARDINA	'92-'97	52119-2B040	1	4.33	4.50	0.0600	
4	TYG019 NA	GRILLE GYM '95	CORONA AT191	'95	53101-20530-C0	5	2.41	3.17	0.0344	
5	TYG019 NB	GRILLE CP/BK '95	CORONA AT191	'95	BRIGHT	5	2.41	3.17	0.0344	
6	TYG019 NC	GRILLE CP	CORONA AT191	'95		5	2.41	3.17	0.0344	
7	TYG181 NA	GRILLE CP/GYM	CORONNA AT181	90-'91	53101-20400	5			0.0500	
8	TYCL019 LA	CORNER LAMP LH	CORONA AT191	'92-'96	81620-20530	40	6.00	8.00	0.2016	
	TYCL019 RA	CORNER LAMP RH	CORONA AT191	'92-'96	81610-20530	40	6.00	8.00	0.2016	
9	TYFL019 LA	FRONT LAMP	TOYOTA CORONA	'95-'96	81620-20640	20	6.00	8.00	0.0664	
	TYFL019 RA	FRONT LAMP	TOYOTA CORONA	'95-'96	81510-20650	20	6.00	8.00	0.0664	
10	53112-20210	SPOTLIGHT COVER	CORONA AT191	'90-'92	53112-20210	1	0.10	0.12	0.0010	
11	TYIF019 LA	INNER FENDER LH	AT171	'90-'92	53876-20250-1	1				
	TYIF019 RA	INNER FENDER RH	AT171	'90-'92	53875-20240-1	1				
12	TYEU019 RA	ENGINE UNDER COVER RH	CORONA AT190	'96-01	51441-20313-4	1				
	TYEU019 LA	ENGINE UNDER COVER LH	CORONA AT190	'96-01	51442-20371-4	1				
13	TYHM181 NA	HOOD MOULDING CP/GYM '90-'92	CORONA AT171	'90-'92	75770-20110	5			0.0149	