

## TOYOTA LAND CRUISER FJ130 2002-2004



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB105 NA	FRONT BUMPER BK	LAND CRUISER	'03-'06	52119-60918(SA)	1	3.94	4.32	0.0500	
2	TYB105 NB	FRONT BUMPER PERL WHITE 070	LAND CRUISER	'03-'06	52119-60550	1	4.00	4.38	0.0600	
3	TYB105 NC	FRONT BUMPER BEIGE UCA46	LAND CRUISER	'03-'06	52119-60550	1	4.00	4.38	0.0600	
4	TYB105 ND	FRONT BUMPER D.GRAY UCA76	LANDCRUISER	'03-'06	52119-60550	1	5.00	5.38	0.0600	
5	TYB105 NE	FRONT BUMPER WHITE 056	LANDCRUISER	'02-'04	52119-60550	1	4.00	4.38	0.0600	
6	TYB105 NF	FRONT BUMPER WITH PRIMED	LAND CRUISER	'03-'06	52119-60550	1	4.00	4.38	0.0600	
7	TYB105 NM	FRONT BUMPER WHITE PERL IRAQ (L-C 25-PTXNIP68 A)	LAND CRUISER	'03-'06	52119-60550	1	4.00	4.38	0.0600	
8	TYB105 NW	FRONT BUMPER WHITE PEARL CS 062	LANDCRUISER	'03-'06	52119-60550	1	4.00	4.38	0.0600	
9	TYB106 NA	REAR BUMPER W/O HOLE	LAND CRUISER FJ200	'98-'07	52159-60161	1	3.77	4.07	0.0600	
10	TYB106 NB	REAR BUMPER W/HOLE PEAR WHITE (070) /BK	LAND CRUISER FJ200	'98-'07	52159-60161	1	4.50	4.80	0.0600	
11	TYB106 NC	REAR BUMPER W/HOLE BEIGE (UCA46) / BK	LAND CRUISER FJ200	'98-'07	52159-60161	1	4.50	4.80	0.0600	
12	TYB106 ND	REAR BUMPER W/HOLE D. GRAY (UCA76) / BK	LAND CRUISER FJ200	'98-'07	52159-60161	1	4.50	4.80	0.0600	
13	TYB106 NE	REAR BUMPER W/HOLE	LANDCRUISER	'98-'07	52159-60161	1	5.00	5.30	0.0600	
14	TYB106 NF	REAR BUMPER W/ HOLE WHITE056	LANDCRUISER	'98-'07	52159-60161	1	4.50	4.80	0.0600	
15	TYB106 NM	REAR BUMPER W/ HOOK HOLE PEARL WHITE IRAQ(L-C 25-PTXNIP68 A)/BK	LAND CRUISER	'98-'07	52159-60161	1	4.50	4.80	0.0600	
16	TYB106 NW	REAR BUMPER W/HOLE WHOTE PEARL CS 062	LANCRUISER	'98-'07	52159-60161	1	4.50	4.50	0.0600	
17	TYG105 NA	GRILLE CP/GYM	FJ130	'02-'03	53101-60270	1	1.68	2.66	0.0500	
18	TYG105 NB	GRILLE GYM	FJ130	'02-'03	53101-60260	1	1.83	2.81	0.0492	



## TOYOTA LAND CRUISER FJ130 2002-2004



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYHL105 LB	HEAD LAMP LH CRYSTAL TYPE	LANDCRUISER	'05	81050-60101	4	8.00	10.00	0.1318	
	TYHL105 RB	HEAD LAMP RH CRYSTAL TYPE	LANDCRUISER	'05	81010-60101	4	8.00	10.00	0.1318	
2	TYCL105 LA	CORNER LAMP LH	LANDCRUISER	'01-'04	81520-60360	40	8.00	10.00	0.2155	
	TYCL105 RA	CORNER LAMP RH	LANDCRUISER	'01-'04	81510-60490	40	8.00	10.00	0.2155	
3	TYFL105 LA	FOG LAMP LH	LAND CRUISER	'01-'04	81221-60030	10	10.00	11.00	0.0900	
	TYFL105 RA	FOG LAMP RH	LAND CRUISER	'01-'04	81211-60110	10	10.00	11.00	0.0900	
4	TYFC105 LA	FOG LAMP COVER W/O HOLE LH	LAND CRUISER	'98-'05	52128-60010/30	50	5.28	6.41		
	TYFC105 RA	FOG LAMP COVER W/O HOLE RH	LAND CRUISER	'98-'05	52127-60010/30	50	5.28	6.41		
5	TYL105 LA	TAIL LAMP LH	LAND CRUISER	'02-'05	81561-60600	10	6.00	8.00	0.1100	
	TYL105 RA	TAIL LAMP RH	LAND CRUISER	'02-'05	81551-60680	10	6.00	8.00	0.1100	
6	TYL105 SB	TAIL LAMP LED TYPE SET 4 PCS	LANDCRUISER	'02-'06		4	5.00	6.00	0.0400	
7	TYRL105 LA	REFLECTOR TAIL LAMP LH	LAND CRUISER	'02-'05	81590-60050	10	6.00	8.00	0.1100	
	TYRL105 RA	REFLECTOR TAIL LAMP RH	LAND CRUISER	'02-'05	81580-60020	10	6.00	8.00	0.1100	
8	TYF105 LA	FENDER LH	LAND CRUISER	'98	53802-6A200	1	4.00	5.08	0.0800	
	TYF105 RA	FENDER RH	LAND CRUISER	'98	53811-60890	1	4.00	5.08	0.0800	
9	TYBP105 NA	SPOILER WHITE 056 (TYBL084 NA)	LANDCRUISER	'02-'04		1	2.50	2.50	0.1023	
10	TYBP105 NB	SPOILER BLACK (202) W/LAMP	LANDCRUISER	'02-'04		1	2.00	2.00	0.1023	
11	TYBP105 NC	SPOILER SIVER GOLD METALIC (1B1)	LANDCRUISER	'02-'04		1	2.00	2.00	0.1023	
12	TYBP105 ND	SPOILER WHITE PEARL (070)	LANDCRUISER	'02-'04		1	2.00	2.00	0.1023	
13	TYBP105 NE	SPOILER GREY METALIC (1D2)	LANDCRUISER	'02-'04		1	2.00	2.00	0.1023	
14	TYBP105 NF	SPOILER RED METALIC (3Q2)	LANDCRUISER	'02-'04		1	2.00	2.00	0.1023	
15	TYBP105 NG	SPOILER GOLD METALIC (4R3)	LAND CRUISER100	'89-'05		1	3.20	3.20	0.1023	
16	TYBP105 NX	SPOILER PRIME COLOR	LANDCRUISER	'02-'04	TYBP105 NX	1	3.21	3.21	0.1023	
17	TYBP105 SP	BRACKET SPOILER	LANDCRUISER	'00-'05		1	2.50	2.50	0.1023	
18	TYIF105 LA	INNER FENDER LH	FJ130	'02-'03	53876-60021	20	4.00	5.00	0.0400	
	TYIF105 RA	INNER FENDER RH	FJ130	'02-'03	53875-60021	20	4.00	5.00	0.0400	

