

## MAZDA PICKUP 2015 BT-50



**1 F. BUMPER 2WD W/BK MOULDING**



**2 F. BUMPER 4WD W/O MOULDING**



**3 GRILLE (2 IN 1) CP/GYM**



**4 BUMPER MOLDING MAT**



**5 BUMPER MOULDING CHROME**



**6 HEAD LAMP RHD BLACK MANUAL**



**7 TAIL LAMP**



**8 REFLECTOR TRUNKLID LAMP**



**9 HOOD LEDGE**



**10 FRONT BUMPER UPPER BEAM**

**11 PLATE(R),SEAL**



**12 CONDENSER**



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	MZB039 NA	F. BUMPER 2WD W/BK MOULDING	MAZDA BT-50	'15	UC2M-50-031E	1	4.50	4.87	0.0600	
2	MZB039 NB	F. BUMPER 4WD W/O MOULDING	BT-50	'11-'12	UG2F-50-031C/AV79-17C831-AD	1	3.85	4.22	0.0600	
3	MZG040 NA	GRILLE (2 IN 1) CP/GYM	BT-50	'15	1D0150710CBM	1	1.60	1.60	0.1198	
4	MZBM039 NA	BUMPER MOLDING MAT	BT50	'12	MZBM039 NA	1	0.35	2.49	0.0210	
5	MZBM039 NB	BUMPER MOULDING CHROME	BT-50	'11-'12	UC2J-50-YE8A/AV79-17D751-AB	1	0.35	2.49	0.0200	
6	MZHL040 LA	HEAD LAMP RHD BLACK MANUAL LH	BT-50	'16	UL4J-51-0L0A	1	3.12	4.80	0.0850	
	MZHL040 RA	HEAD LAMP RHD BLACK MANUAL RH	BT-50	'16	UL4J-51-0K0A	1	3.12	4.80	0.0850	
	MZHL040 LB	HEAD LAMP LHD BLACK MANUAL LH	BT-50	'16	UL4L-51-0L0A	1	3.12	4.80	0.0850	
	MZHL040 RB	HEAD LAMP LHD BLACK MANUAL RH	BT-50	'16	UL4L-50-0K0A	1	3.12	4.80	0.0850	
7	MZL040 LA	TAIL LAMP LH	BT-50	'16	UL4J-51-160A	10	10.00	11.00	0.1000	
	MZL040 RA	TAIL LAMP RH	BT-50	'16	UL4J-51-150A	10	10.00	11.00	0.1000	
8	MZRL040 LA	REFLECTOR TRUNKLID LAMP LH	BT-50	'15	UL4J-51-3G0A					
	MZRL040 RA	REFLECTOR TRUNKLID LAMP RH	BT-50	'15	UL4J-51-3F0A	1				
9	UC9M-54-210N	HOOD LEDGE LH	BT50/DURATORQUE	'14-'15	UC9M-54-210N	1				
	UC9M-53-210J	HOOD LEDGE RH	BT50/DURATORQUE	'14-'15	UC9M-53-210J	1				
10	UC9M-54-260E	FRONT BUMPER UPPER BEAM LH	RANGER	'15	UC9M-54-260E					
	UC9M-53-260E	FRONT BUMPER UPPER BEAM RH	RANGER	'15	UC9M-53-260E	1	1.44	1.46		
11	UC2B-56-251C	PLATE(R),SEAL	BT50	'14	UC2B-56-251C	1	0.35	0.45	0.0271	
	UC2B-56-253C	PLATE(L),SEAL	BT50	'14	UC2B-56-253C	1	0.35	0.44	0.0271	
12	UC9M-61-480A	CONDENSER	BT50/DURATORQUE	'14-'15	AB39-19-710AB	1	4.00	6.00	0.0600	