

MITSUBISHI PAJERO V73 2004-2006



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	MBB061 NA	FRONT BUMPER BK W/O WASHER HOLE	PAJERO	'04-'05	MN133639XA	1	3.58	3.91	0.0600	
2	MBB061 NB	FRONT BUMPER BK W/ WASHER HOLE	PAJERO	'04-'05	MN133639XA/MN133637	1	3.60	3.93	0.0600	
3	MBB062 NA	REAR BUMPER	PAJERO V73	'04-'06	MN133663XB	1	5.00	5.30	0.0700	
4	MBG061 NA	GRILLE CP/BK	PAJERO	'04-'05	MN117202HA	1	1.50	1.50	0.0467	
5	MBG061 NB	GRILLE BK	PAJERO V73	'04-'05	MN117202WA	1	1.18	1.23	0.0467	
6	MBHL061 LA	HEAD LAMP CHROME LH	PAJERO V73	'04-'06	MN133753	4	16.50	19.00	0.2867	
	MBHL061 RA	HEAD LAMP CHROME RH	PAJERO V73	'04-'06	MN133754	4	16.50	19.00	0.2867	
7	MBFL061 LA	FOG LAMP LH	PAJERO V73	'04-'06	MN133758L	20	11.00	13.00	0.0562	
	MBFL061 RA	FOG LAMP RH	PAJERO V73	'04-'06	MN133758R	20	11.00	13.00	0.0562	
8	MBSL061 LA	SIDE LAMP LH	PAJERO V73	'04	MR522027L	100	15.00	16.00	0.2938	
	MBSL061 RA	SIDE LAMP RH	PAJERO V73	'04	MR522027R	100	15.00	16.00	0.2938	
9	MABL062 LA	REAR BUMPER LAMP LH	PAJERO V73	'04-'06	MN133775	50	6.00	19.80	0.1962	
	MABL062 RA	REAR BUMPER LAMP RH	PAJERO V73	'04-'06	MN133776	50	6.00	19.80	0.1962	
10	MBL061 LA	TAIL LAMP LH EU TYPE(2 SOCKETS)	PAJERO V73	'04-'06	MN133763	10	8.00	19.20	0.2995	
	MBL061 RA	TAIL LAMP RH EU TYPE(1 MIDDLE SOCKET)	PAJERO V73	'04-'06	MN133764	10	8.00	19.20	0.2995	
11	MBL063 LA	TAIL LAMP LH	PAJERO	'03-'07	MR548043	10	15.50	16.00	0.3089	
	MBL063 RA	TAIL LAMP RH	PAJERO	'03-'07	MR548044	10	15.50	16.00	0.3089	
12	MBL063 LC	TAIL LAMP CRYSTAL LH	PAJERO	'03-'07	MR981289	10	16.50	18.00	0.2053	
	MBL063 RC	TAIL LAMP CRYSTAL RH	PAJERO	'03-'07	MR981290	10	16.50	18.00	0.2053	
13	MBMR061 LA	BACKUP MIRROR LH	PAJERO	'03-'06	MR652073	1	1.50	2.00	0.2016	
	MBMR061 RA	BACKUP MIRROR RH	PAJERO	'03-'06	MR652075	1	1.50	2.00	0.2016	
14	MBF061 LA	FENDER W/SIDE LAMP HOLE LH	PAJERO V73	'04	MR535753	1	3.82	4.62	0.0800	
	MBF061 RA	FENDER W/SIDE LAMP HOLE RH	PAJERO V73	'04	MR535756	1	3.82	4.57	0.0800	
15	MBH061 NA	HOOD W/O HOLE	PAJERO V73	'04	MR485951	1	18.50	20.00	0.1800	

