

TOYOTA ECHO '2004



1 F. BUMPER



2 R. BUMPER



3 FOG LAMP COVER



4 BUMPER MOULDING CP



5 HEAD LAMP LHD



6 TAIL LAMP



7 FENDER W/O S.L HOLE




8 FENDER W. S.L. HOLE



9 HOOD



10 RADIATOR SUPPORT



11 FRONT BUMPER SUPPORT



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB143 NA	F. BUMPER	ECHO	04-'05	52119-52220	1	3.75	4.12	0.0600	
2	TYB144 NA	R. BUMPER	ECHO	04-'05	52159-52340	1	4.06	4.44	0.0600	
3	TYFC143 LA	FOG LAMP COVER LH	ECHO	04-'05	52438-52030	50	1.90	3.03	0.0300	
	TYFC143 RA	FOG LAMP COVER RH	ECHO	04-'05	52437-52030	50	1.90	3.03	0.0300	
4	TYGM143 NA	BUMPER MOULDING CP	ECHO	04-'05	52711-52020	20			0.0200	
5	TYHL143 RA	HEAD LAMPLHD RH	ECHO	04-'05	81130-52320	10	16.00	15.00	0.2300	
	TYHL143 LA	HEAD LAMP LHD LH	ECHO	04-'05	81170-52320	4	6.00	8.00	0.1616	
6	TYL143 LA	TAIL LAMP LH	ECHO	04-'05	81560-52310	10	10.00	13.55	0.1725	
	TYL143 RA	TAIL LAMP RH	ECHO	04-'05	81550-52330	10	10.00	13.55	0.1725	
7	TYF143 LA	FENDER W/O S.L.HOLE LH	ECHO	04-'05	53802-52030	1	3.00	3.05	0.0600	
	TYF143 RA	FENDER W/O S.L.HOLE RH	ECHO	04-'05	53801-52030	1	3.00	3.05	0.0600	
8	TYF143 LB	FENDER W. S.L. HOLE LH	ECHO	04-'05	53811-52150	1	3.00	3.05	0.0600	
	TYF143 RB	FENDER W. S.L. HOLE RH	ECHO	04-'05	52812-52150	1	3.00	3.05	0.0600	
9	TYH143 NA	HOOD	ECHO	04-'05	53301-52140	1	8.00	10.00	0.1584	
10	TYR143 NA	RADIATOR SUPPORT	ECHO	04-'05	53201-52131	1				
11	TYBS143 LA	FRONT BUMPER SUPPORT LH	ECHO	03-05	52116-52040	1	0.11	0.11		
	TYBS143 RA	FRONT BUMPER SUPPORT RH	ECHO	03-05	52115-52040	1	0.11	0.11		