

TOYOTA HIACE YH133V 1993-1999



1 GRILLE HORIZONTAL TYPE GY



2 GRILLE HORIZONTAL TYPE CP



3 GRILLE HONEY TYPE GRAY



4 GRILLE



5 FRONT BUMPER NARROW TYPE



6 FRONT BUMPER BROAD TYPE



7 HEAD LAMP



8 HEAD LAMP CRYSTAL



9 CORNER LAMP SEAL BEAM



10 CORNER LAMP



11 CORNER LAMP CHROME



12 LENS MOULDING AMBER



13 LENS MOULDING CLEAR



14 FRONT PANEL ASSY



15 CONDENSER



NO	CODE	DESCRIPTION		MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYG033 NA	GRILLE HORIZONTAL TYPE GY	KENYA	HIACE U-LH113V	'93-'99	53100-26060	5	5.46	7.46	0.1465	
2	TYG033 NB	GRILLE HORIZONTAL TYPE CP		HIACE	'93-'99	PERFORMANCE	5	5.44	7.45	0.1465	
3	TYG035 NA	GRILLE HONEY TYPE GRAY		HIACE U-LH113V	'98-'04	53111-26210	10	6.00	6.40	0.2250	
4	TYG035 NB	GRILLE		HIACE VAN	'93-'94		5			0.1254	
5	TYB033 NA	FRONT BUMPER NARROW TYPE	KENYA	HIACE U-LH113V	'93-'99	52119-95J21	1	2.64	2.87	0.0600	
6	TYB035 NA	FRONT BUMPER BROAD TYPE		HIACE U-UT113	'98-'04	52119-26300	1	2.00	2.24	0.0300	
7	TYHL033 LA	HEAD LAMP LH		HIACE	'93-'94	81170-26060	7	12.00	13.00	0.1000	
	TYHL033 RA	HEAD LAMP RH		HIACE	'93-'94	81130-26060	7	12.00	13.00	0.1000	
8	TYHL033 LB	HEAD LAMP LH CRYSTAL		HIACE	'93-'94		10				
	TYHL033 RB	HEAD LAMP RH CRYSTAL		HIACE VAN	'93-'94		10				
9	TYCL031 LA	CORNER LAMP LH SEAL BEAM		HIACE YH133V	'93-'95	81620-95J03	10	6.00	8.00	0.0732	
	TYCL031 RA	CORNER LAMP RH SEAL BEAM		HIACE YH133V	'93-'95	81610-95J03	10	6.00	8.00	0.0732	
10	TYCL033 LA	CORNER LAMP LH	KENYA	HIACE YH103	'93-'94	81620-26030	20	10.10	10.80	0.1400	
	TYCL033 RA	CORNER LAMP RH	KENYA	HIACE YH103	'93-'94	81610-26030	20	10.10	10.80	0.1400	
11	TYCL033 LB	CORNER LAMP CHROME LH		HIACE	'93-'99		20	8.00	10.00	0.1269	
	TYCL033 RB	CORNER LAMP CHROME RH		HIACE	'93-'99		20	8.00	10.00	0.1269	
12	TYLM033 LA	LENS MOULDING AMBER LH		HIACE YH133V	'93-'99		20	8.00	10.00	0.1200	
	TYLM033 RA	LENS MOULDING AMBER RH		HIACE YH133V	'93-'99		10	8.00	5.90	0.0771	
13	TYLM033 LB	LENS MOULDING CLEAR LH		HIACE YH133V	'93-'99		20	8.00	10.00	0.1200	
	TYLM033 RB	LENS MOULDING CLEAR RH		HIACE YH133V	'93-'99		20	8.00	10.00	0.1200	
14	TYFP055 NA	FRONT PANEL ASSY		HIACE	'94-'95	55701-95J22	1	12.00	13.00	0.1500	
15	CL3054	CONDENSER		HIACE	1998-00	88460-26330	1	4.00	5.60	0.0389	

