

TOYOTA HIACE 2019



1 FRONT BUMPER W/FINISHER 3 IN 1



2 FRONT BUMPER FINISHER LOWER



3 FRONT BUMPER FINISHER UPPER



4 GRILLE SV/BK



5 GRILLE CP/BK



6 REAR BUMPER W/O MUFFLER HOLE



7 FOG LAMP COVER W/O HOLE



8 FOG LAMP COVER W/HOLE



9 HOOD MOULDING SV

10 HOOD MOULDING CP

11 FRONT BUMPER BRACKET



12 REAR BUMPER BRACKET LONG



13 REAR SIDE BUMPER BRACKET



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYB237 NA	FRONT BUMPER W/FINISHER 3 IN 1	HIACE	'19	52119-26870(B) 53112-26120(BF) 53113-26070(BF)	1	4.65	5.10	0.0700	
2	TYBF237 LA	FRONT BUMPER FINISHER LOWER	HIACE	'19	53112-26120	1	0.25	0.25	0.0010	
3	TYBF237 UA	FRONT BUMPER FINISHER UPPER	HIACE	'19	53113-26070	1	0.25	0.25	0.0010	
4	TYG237 NA	GRILLE SV/BK	HIACE	'19	53101-26210	5	6.14	8.10	0.1533	
5	TYG237 NB	GRILLE CP/BK	HIACE	'19	53101-26230	5	6.14	8.10	0.1533	
6	TYB238 NA	REAR BUMPER W/O MUFFLER HOLE	HIACE	'19	52159-26620	1	2.51	2.81	0.0500	
7	TYFC237 LA	FOG LAMP COVER W/O HOLE LH	HIACE	'19	52040-26010	20	9.20	9.80	0.1370	
	TYFC237 RA	FOG LAMP COVER W/O HOLE RH	HIACE	'19	52030-26010	20	9.20	9.80	0.1370	
8	TYFC237 LB	FOG LAMP COVER W/HOLE LH	HIACE	'19	52040-26020	1				
	TYFC237 RB	FOG LAMP COVER W/HOLE RH	HIACE	'19	52030-26020	1				
9	TYHM237 NA	HOOD MOULDING SV	HIACE	'19	53122-26020	1				
10	TYHM237 NB	HOOD MOULDING CP	HIACE	'19	53122-26040	1	0.04	0.04	0.0010	
11	TYBS237 LA	FRONT BUMPER BRACKET LH	HIACE	'19	52116-26190	1	0.15	1.28	0.0696	
	TYBS237 RA	FRONT BUMPER BRACKET RH	HIACE	'19	52115-26190	1	0.15	1.28	0.0696	
12	TYBS238 LA	REAR BUMPER BRACKET LONG LH	HIACE	'19	52156-26020	1	4.65	5.10		
	TYBS238 RA	REAR BUMPER BRACKET LONG RH	HIACE	'19	52155-26160	100	9.76	10.89	0.0670	
13	TYBS238 LM	REAR SIDE BUMPER BRACKET LH	HIACE	'19	52158-26020	100	9.66	10.79	0.0670	
	TYBS238 RM	REAR SIDE BUMPER BRACKET RH	HIACE	'19	52157-26020	100	9.76	10.89	0.0670	