


TOYOTA HILUX RN20 / RN25 1974- 1978



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYG005 LA	GRILLE GY '74-'78	RN25	'74-'78	53113-89804-03	5	5.86	7.08	0.0818	
	TYG005 RA	GRILLE GY '74-'78	RN25	'74-'78	53112-89806-03	5	5.84	7.07	0.0818	
2	TYG005 LB	GRILLE CP '74-'78	RN25	'74-'78	53113-89809-04	1	1.10	2.33	0.0353	
	TYG005 RB	GRILLE CP '74-'78	RN25	'74-'78	53112-89807-04	1	1.09	2.32	0.0353	
3	TYP005 NA	VALANCE PANEL '74-'78	RN25	'74-'78	53911-89102	5	5.00	6.00	0.0500	
4	TYFL005 LA	FRONT LAMP 2 COLOR LH	RN25	'72-'77	81520-89805	50	6.00	8.00	0.0664	
	TYFL005 RA	FRONT LAMP 2 COLOR RH	RN25	'72-'77	81510-89805	25	6.00	8.00	0.0664	
5	TYFL005 LB	FRONT LAMP ALL AMBER LH	HILUX RN25	'78	81520-89804	50	6.00	8.00	0.0600	
	TYFL005 RB	FRONT LAMP ALL AMBER RH	HILUX RN25	'78	81510-89804	50	6.00	8.00	0.0664	
6	TYSL005 LA	SIDE LAMP (CP) LH	RN20	'74-'77	81740-89805	200	8.00	10.00	0.0500	
	TYSL005 RA	SIDE LAMP (CP) RH	RN20	'74-'77	81730-89805	200	8.00	10.00	0.0500	
7	TYSL005 LB	SIDE LAMP (BK) LH	RN25	'77-'78	81520-89812	200	8.00	10.00	0.0500	
	TYSL005 RB	SIDE LAMP (BK) RH	RN25	'77-'78	81510-89812	200	8.00	10.00	0.0500	
8	TYL005 LA	TAIL LAMP RN25	RN25	'74-'78	81560-89812	10	8.00	10.00	0.0700	
	TYL005 RA	TAIL LAMP RN25	RN25	'74-'78	81550-89812	10	8.00	10.00	0.0700	
9	TYE005 LA	R.CORNER PANEL '74-'78	RN25	'74-'78	65560-89106	1	2.00	4.00	0.0075	
	TYE005 RA	R.CORNER PANEL '74-'78	RN25	'74-'78	65550-89106	1	2.00	4.00	0.0075	
10	TYLP005 NA	LICENSE PLATE LAMP	TOYOTA HILUX RN25	'72-'77		50	6.00	7.00	0.0500	
11	TYRL005 NA	ROOM LAMP	HILUX RN25	'72-'77		1				
12	TYRM005 NA	ROOM MIRROR	TOYOTA HILUX	74-78		1				
13	TYF005 LA	FENDER E.D.P. '74-'78	RN20-25	'74-'78	53802-89131 (3) (26)	1	4.00	4.86	0.0600	
	TYF005 RA	FENDER E.D.P. '74-'78	RN20-25	'74-'78	53801-89131 (3) (26)	1	4.00	4.86	0.0600	
14	TYFD005 LA	F. DOOR COMPLETE LH	E.D.P. RN25	'72-'77	67002-89113	1	17.00	17.70	0.1500	
	TYFD005 RA	F.DOOR COMPLETE RH	E.D.P. RN25	'72-'77	67001-89112	1	17.00	17.70	0.1500	
15	TYK005 LA	DOOR SKIN '74-'78	RN25	'74-'78	67112-89109	5	6.00	7.00	0.0500	
	TYK005 RA	DOOR SKIN '74-'78	RN25	'74-'78	67111-89112	5	6.00	7.00	0.0500	

TOYOTA HILUX RN20 / RN25 1974- 1978



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYSP005 LA	SIDE PANEL LONG LH	RN25	'74-'78	65600-89114	2	8.00	10.00	0.0800	
	TYSP005 RA	SIDE PANEL LONG RH	RN25	'74-'78	65500-89111	2	8.00	10.00	0.0800	
2	TYH005 NA	HOOD	RN25	'74-'78	53301-89107/9	1	13.00	14.00	0.1000	
3	TYTB005 NA	REAR TAIL BODY LONG 5 HOOKS	RN25	'74-'78	66000-89125	1	150.00	160.00	3.0000	
4	TYTB005 NB	REAR TAIL BODY	RN25	'74-'78	66000-89126	1	140.00	150.00	2.5000	
5	TYT005 NA	REAR GATE	RN25	'74-'78	65700-89112	1	10.00	11.00	0.0500	
6	TYHL005 LA	HOOD LEDGE RN25	RN25	'74-'78	53702-89108	1	3.00	3.00	0.0300	
	TYHL005 RA	HOOD LEDGE RN25 '74-'78	RN25	'74-'78	53701-89110	1	3.00	3.00	0.0300	
7	TYWH005 LA	PANEL WHEEL HOUSE RN25	RN25	'74-'78	65652-89102	1	1.50	1.50	0.0200	
	TYWH005 RA	PANEL WHEEL HOUSE RN25	RN25	'74-'78	65651-89102	1	1.50	1.50	0.0200	
8	TYBT005 NA	BOLSTER TAIL	RN25	'74-'78	65240-89105	1	8.35	8.35	0.0314	
9	TYR005 NA	RADIATOR SUPPORT '74-'78	RN25	'74-'78	53201-89108(53802-89113)	1	4.00	4.72	0.0600	
10	EFB005 TY	ENGINE FAN BLADE <small>MAT/WT</small>	RN25	'74-'78	16361-31021	20	4.72	4.75	0.1260	
11	TYLH005 LA	LAMP HOUSING LH	HILUX RN25	'72-'77	81150-89809	20	5.00	6.00	0.0600	
	TYLH005 RA	LAMP HOUSING RH	HILUX RN25	'72-'77	81110-89810	20	1.00	2.00	0.0600	
12	TYFP005 LA	FRONT LID SIDE PANEL LH	RN20-25	'72-'78	65621-89103	5	5.00	6.00	0.0500	
	TYFP005 RA	FRONT LID SIDE PANEL RH	RN20-25	'72-'78	65621-89103	5	5.00	6.00	0.0500	
13	TYRP005 LA	REAR LID SIDE PANEL LH	RN20-25	'72-'78	65624-89103	5	5.00	6.00	0.0500	
	TYRP005 RA	REAR LID SIDE PANEL RH	RN20-25	'72-'78	65623-89103	5	5.00	6.00	0.0500	
14	TYSO005 LA	SILL BODY SIDE OUTER LH (บันได)	RN25		61412-89102	1	8.00	10.00	0.0200	
	TYSO005 RA	SILL BODY SIDE OUTER RH (บันได)	RN25		61411-89102	1	8.00	10.00	0.0200	