


TOYOTA HILUX PICK UP 2WD '1989-'1993



1 F.BUMPER (BK) MTX



2 F.BUMPER (CP) W/O HOLE



3 F.BUMPER (CP) W/HOLE



4 GRILLE



5 GRILLE



6 GRILLE



7 GRILLE



8 GRILLE



9 GRILLE



10 CORNER LAMP CP



11 CORNER LAMP GY



12 H/L DOOR



13 H/L DOOR



14 H/L DOOR



15 LAMP HOUSING



NO	CODE	DESCRIPTION		MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYIB006 NA	F.BUMPER (BK) MTX	BK	YN100/85	'89-'93	52101-89107/8	1	3.00	3.95	0.0300	
2	TYIB007 NA	F.BUMPER (CP) W/O HOLE	CP	YN100/85	'89-'93	52101-89109/35070	1	3.50	3.94	0.0256	
3	TYIB007 NB	F.BUMPER (CP) W/HOLE	CP	YN100/85	'89-'93	52101-35240	1	3.50	3.94	0.0256	
4	TYG054 NA	GRILLE	GY/BK	HILUX2WD	'89-'91	53111-89135	5	0.01	2.17	0.1800	TO1200137
5	TYG054 NB	GRILLE	BK	HILUX2WD	'89-'91	53111-89130 (1)	5	7.91	10.07	0.1800	TO1200134
6	TYG054 ND	GRILLE	CP	HILUX2WD	'89-'91	53111-89131	5	5.52	7.68	0.1800	TO1200222
7	TYG059 NA	GRILLE	CP/BK	HILUX YN80	'89-'93	53111-89132	5	5.52	7.07	0.1199	TO1200135
8	TYG059 NB	GRILLE	GY/BK	HILUX YN80	'89-'93	53111-89133	5	5.52	7.07	0.1199	TO1200136
9	TYG059 ND	GRILLE	CP	HILUX YN80	'89-'93	53111-89132	5	5.52	7.07	0.1199	
10	TYCL059 LA	CORNER LAMP CP LH	CP	HILUX RN80	'89-'91	81620-89172	20			0.0753	
	TYCL059 RA	CORNER LAMP CP RH	CP	HILUX 'RN80	'89-'91	81610-89172	20			0.0753	
11	TYCL059 LB	CORNER LAMP GY LH	GY	HILUX RN80	'89-'91	81620-89171	20			0.0753	
	TYCL059 RB	CORNER LAMP GY RH	GY	HILUX RN80	'89-'91	81610-89171	20			0.0753	
	TYZ059 RA	CORNER LAMP LENS RH		PICK UP	'89-'93	81611-89171	100			0.0695	
	TYZ059 LA	CORNER LAMP LENS LH		PICK UP	'89-'93	81621-89171	100			0.0695	
12	TYD059 LA	H/L DOOR LH	CP/BK	HILUX YN80	'89-'93	53132-89116	20	3.48	3.50	0.0753	TO2512108
	TYD059 RA	H/L DOOR RH	CP/BK	HILUX YN80	'89-'93	53131-89117	20	4.95	4.97	0.0753	TO2513110
13	TYD059 LB	H/L DOOR LH	GY/BK	HILUX YN80	'89-'93	53132-89116	20	4.95	4.97	0.0800	TO2512109
	TYD059 RB	H/L DOOR RH	GY/BK	HILUX YN80	'89-'93	53131-89117	20	4.71	4.72	0.0800	TO2513111
14	TYD059 LD	H/L DOOR LH	CP	HILUX YN80	'89-'93	53132-89116	20	4.95	4.97	0.0753	
	TYD059 RD	H/L DOOR RH	CP	HILUX YN80	'89-'93	53131-89117	20	4.71	4.72	0.0800	
15	TYLH057 LA	LAMP HOUSING LH		YN100	'89-'95	81150-89158-C1	40	8.00	9.00	0.0781	
	TYLH057 RA	LAMP HOUSING RH		YN100	'89-'95	81110-89158-C1	40	8.00	9.00	0.0781	

TOYOTA HILUX PICK UP 2WD '1989-'1993

1 TAIL LAMP BK	2 TAIL LAMP	3 TAIL LAMP CP
		
4 CORNER PANEL	5 DOOR MIRROR	6 DOOR MIRROR CHROME
		
7 SIDE PANEL LONG	8 REAR GATE W/ TOYOTA MARK S. OPEN NER	9 REAR GATE W/O TOYOTA MARK S. OPEN NER
		
10 REAR GATE W/ TOYOTA MARK MIDDLE OPENNER	11 RADIATOR SUPPORT	12 VALANCE PANEL
		
13 BUMPER STAY	14 RADIATOR FAN SHROUD	15 REAR TAIL BODY 5 HOOK
		
16 REAR TAIL BODY 4 HOOK		

NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYL057 LA	TAIL LAMP BK LH	YN100	'89-93	81560-89163	20	5.07	6.00	0.1076	
	TYL057 RA	TAIL LAMP BK RH	YN100	'89-93	81550-89163	10	5.07	6.00	0.0536	
2	TYL057 LB	TAIL LAMP LH	HILUX	'89-93	81560-89163	20	0.59	0.64	0.1076	
	TYL057 RB	TAIL LAMP RH	HILUX	'89-93	81550-89163	20	0.59	0.64	0.1076	
3	TYL057 LC	TAIL LAMP CP LH	YN100	'89-'93	81560-89163	10	5.00	5.90	0.0527	
	TYL057 RC	TAIL LAMP CP RH	YN100	'89-'93	81550-89163	10	5.00	5.90	0.0527	
4	TYE059 LA	CORNER PANEL LH	YN80	'89-'93	65506-89109-C3	1	10.00	10.62	0.0132	
	TYE059 RA	CORNER PANEL RH	YN80	'89-'93	65505-89109-C3	1	10.00	10.62	0.0132	
5	TYMR057 LA	DOOR MIRROR LH	YN85	'93	68112-35071-1	10			0.0600	
	TYMR057 RA	DOOR MIRROR RH	YN85	'93	68111-35071-1	10			0.0600	
6	TYMR057 RB	DOOR MIRROR CHROME	YN85	'93	68111-35071-1	10			0.0600	
	TYMR057 LB	DOOR MIRROR CHROME	YN85	'93	68112-35071-1	10			0.0600	
7	TYSP059 LA	SIDE PANEL LONG LH	YN85,YN145	'89-'98		2	15.00	16.00	0.0800	
	TYSP059 RA	SIDE PANEL LONG RH	YN85,YN145	'89-'98		2	15.00	16.00	0.1200	
	TYSP059 LB	SIDE PANEL SHORT	HILUX	'89-'93	85817-89139	2	8.00	10.00	0.0800	
	TYSP059 RB	SIDE PANEL SHORT	HILUX	'89-'93	85816-89141	2	8.00	10.00	0.0800	
8	TYT059 NA	REAR GATE W/ TOYOTA MARK	S. OPEN NER YN85	'89-'93	65700-89153-C3/ 89000/35110	1	12.00	13.00	0.0600	
9	TYT059 NB	REAR GATE W/O TOYOTA MARK	S. OPEN NER YN85	'89-'93	65700-89148	1	12.00	13.00	0.0600	
10	TYT059 NC	REAR GATE W/ TOYOTA MARK	MIDDLE OPENNER YN85	'89-'95	65700-35120	1	12.00	13.00	0.0600	
11	TYR057 NA	RADIATOR SUPPORT	YN100	'89-'93	53201-89118	1	6.00	7.00	0.0400	
12	TYP059 NA	VALANCE PANEL	YN80	'89-'93	53911-89114	1	2.00	2.50	0.0150	
13	TYBS057 LA	BUMPER STAY LH	MIGHTYX	'89-'95	52012-89115/ 35060-1	10	6.00	7.00	0.0300	
	TYBS057 RA	BUMPER STAY RH	MIGHTYX	'89-'95	52011-89115/ 35060-1	10	6.00	7.00	0.0300	
14	TYRF057 NA	RADIATOR FAN SHROUD	HILUX YN100	'93-'94	16261-54040	1	0.40	0.40	0.0020	
15	TYTB059 NA	REAR TAIL BODY 5 HOOK	RN85	'89-'93		1	150.00	160.00	3.5000	
16	TYTB059 NB	REAR TAIL BODY 4 HOOK	RN85	'89-'93		1	140.00	150.00	2.5000	