

TOYOTA HILUX PICK UP 2WD 1993-1994 (MIGHTY X)



1 GRILLE CP/BK '92-'93



2 GRILLE GY/BK '92-'93



3 GRILLE GY '92-'93



4 GRILLE BK '92-'93



5 GRILLE CP '92-'93



6 GRILLE CP/GYM



7 GRILLE CP / GOLD 2 IRAN



8 F.BUMPER(BK) MTX



9 F.BUMPER(CP)W/O HOLE



10 F.BUMPER(CP) W/Hole



11 VALANCE PANEL MTX



12 CORNER LAMP CP



13 CORNER LAMP GYM



14 CORNER LAMP GY/CLEAR



15 CORNER LAMP CP/WT

16 FRONT LAMP ORANGE



17 FRONT LAMP PERFORMANCE CP/ALL CL



18 LICENSE PLATE LAMP



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYG057 NA	GRILLE CP/BK '92-'93	HILUX YN85	'92-'93	53111-35070	5	8.38	10.53	0.1842	
2	TYG057 NB	GRILLE GY/BK '92-'93	HILUX YN85	'92-'93	53111-35060	5	8.38	10.53	0.1842	
3	TYG057 NC	GRILLE GY '92-'93	HILUX YN85	'92-'93	53111-35080	5	8.38	10.53	0.1842	
4	TYG057 ND	GRILLE BK '92-'93	HILUX YN85	'92-'93	53111-35080	5	8.38	10.53	0.1842	
5	TYG057 NE	GRILLE CP '92-'93	HILUX YN85	'92-'93	BRIGHT	5	8.38	10.53	0.1842	
6	TYG057 NF	GRILLE CP/GYM	HILUX YN85	'92-'93		5	8.38	10.53	0.1842	
7	TYG057 NI	GRILLE CP / GOLD 2 IRAN	HILUX YN85	'92-'93	53111-35080	5	8.38	10.53	0.1842	
8	TYIB006 NA	F.BUMPER(BK) MTX	YN100/85	'89-'93	52101-89107/8	1	3.00	3.95	0.0300	
9	TYIB007 NA	F.BUMPER(CP)W/O HOLE	YN100/85	'89-'93	52101-89109	1	3.50	3.94	0.0256	
10	TYIB007 NB	F.BUMPER(CP) W/Hole	YN100/85	'89-'93	52101-35240	1	3.50	3.94	0.0256	
11	TYP057 NA	VALANCE PANEL MTX	YN100	'92-'95	53911-35010	1	2.00	2.00	0.0300	
12	TYCL057 LA	CORNER LAMP CP	CP/WT YN85	'93-'95	81620-35051	20	6.00	7.00	0.0639	
	TYCL057 RA	CORNER LAMP CP	CP/WT YN85	'93-'95	81610-35050	20	6.00	7.00	0.0600	
13	TYCL057 LB	CORNER LAMP GYM	GYM/WT YN85	'93-'95	81620-35060	20	6.00	7.00	0.0639	
	TYCL057 RB	CORNER LAMP GYM	GYM/WT YN85	'93-'95	81610-35060	20	6.00	7.00	0.0639	
14	TYCL057 LC	CORNER LAMP GY/CLEAR	GY/WT YN85	'93-'95	81620-35270	20	6.00	7.00	0.0639	
	TYCL057 RC	CORNER LAMP GY/CLEAR	GY/WT YN85	'93-'95	81610-35270	20	6.00	7.00	0.0639	
15	TYCL057 LD	CORNER LAMP CP/WT	CLEAR/CLEAR HILUX	'93-'95	81620-35270	20	6.00	7.00	0.0551	
	TYCL057 RD	CORNER LAMP CP/WT	CLEAR/CLEAR HILUX	'93-'95	81610-35270	20	6.00	7.00	0.0551	
16	TYFL057 LA	FRONT LAMP LH ORANGE	MAT/WTGY LN85	'91-'95	81520-89133	40	5.20	6.40	0.0664	
	TYFL057 RA	FRONT LAMP RH ORANGE	MAT/WTGY LN85	'91-'95	81510-89133	40	5.20	6.40	0.0664	
17	TYFL057 LB	FRONT LAMP LH PERFORMANCE CP/ALL CLEAR	LN85	'91-'95	81520-89133	40	8.00	10.00	0.0664	
	TYFL057 RB	FRONT LAMP RH PERFORMANCE CP/ALL CLEAR	LN85	'91-'95	81510-89133	40	8.00	10.00	0.0664	
18	TYLP057 NA	LICENSE PLATE LAMP	HILUX YN85	'89-'95	81270-89124	50	4.00	6.00	0.0600	

TOYOTA HILUX PICK UP 2WD 1993-1994 (MIGHTY X)



NO	CODE	DESCRIPTION	MODEL	YEAR	OEM	PCS	NW	GW	M3	PART LINK
1	TYL057 LA	TAIL LAMP BK LH	YN100	'89-93	81560-89163	20	5.07	6.00	0.1076	
	TYL057 RA	TAIL LAMP BK RH	YN100	'89-93	81550-89163	10	5.07	6.00	0.0536	
2	TYL057 LB	TAIL LAMP CLEAR/RED LH	TOY HILUX		81560-89163	20	0.59	0.64	0.1076	
	TYL057 RB	TAIL LAMP CLEAR/RED RH	TOY HILUX		81550-89163	20	0.59	0.64	0.1076	
3	TYL057 LC	TAIL LAMP CP LH	YN100	'89-'93	81560-89163	10	5.00	5.90	0.0527	
	TYL057 RC	TAIL LAMP CP RH	YN100	'89-'93	81550-89163	10	5.00	5.90	0.0527	
4	TYMR057 LA	DOOR MIRROR LH	YN85	'93	68112-35071-1	10	6.00	8.00	0.0600	
	TYMR057 RA	DOOR MIRROR RH	YN85	'93	68111-35071-1	10	6.00	8.00	0.0600	
5	TYMRO57 LB	DOOR MIRROR CHROME	HILUX PICK-UP 2WD	'89-'95	20-B322-A5-6F	10	6.00	8.00	0.0600	
	TYMRO57 RB	DOOR MIRROR CHROME	HILUX PICK-UP 2WD	'89-'95	68111-35071-1	10	6.00	8.00	0.0600	
6	TYRM057 NA	ROOM MIRROR	TOYOTA YN100			20	6.00	8.00	0.0600	
7	TYIF057 LA	INNER FENDER '89-'95	HILUX YN85	'89-'95	53876-89100-4 / 105	20	9.15	9.15	0.0600	
	TYIF057 RA	INNER FENDER '89-'95	HILUX YN85	'89-'95	53875-89100-4 / 105	20	9.15	9.15	0.0600	
8	TYF057 LA	FENDER E.D.P. LH	YN85	'89-'93	53812-04040(89193)	1	3.00	3.52	0.0600	
	TYF057 RA	FENDER E.D.P. RH	YN85	'89-'93	53811-04040(89202)	1	3.00	3.52	0.0600	
9	TYK057 LA	DOOR SKIN '92-'93	HILUX MIGHTY X	'92-'93	67112-89212	5	6.00	8.00	0.0400	
	TYK057 RA	DOOR SKIN '92-'93	HILUX MIGHTY X	'92-'93	67111-89207	5	6.00	8.00	0.0400	
10	TYSP057 LA	SIDE PANEL LH	HILUX YN85	'93		2	10.00	11.50	0.0792	
	TYSP057 RA	SIDE PANEL RH	HILUX YN85	'93		2	10.00	11.50	0.0792	
11	TYH057 NA	HOOD E.D.P.MIGHTY-X	MIGHTY-X	'89-'96	53301-89124 (04020)	1	13.50	15.75	0.1473	
12	63111-89122	ROOF 4 DOOR 4WD	YN85/LN85	'92	63111-89122	1	14.00	17.80	0.3499	
13	TYT057 NA	REAR GATE '93-'94	YN100	'93-'94	65700-89156-6	1	14.00	15.00	0.0600	
14	TYT057 NC	REAR GATE W/TOYOTA MARK W/HOOK	YN100	'93-'94		1	14.00	15.00	0.0600	
15	TYWH057 LA	PANEL WHEEL HOUSE HILUX '89-'93	HILUX PICK UP 2WD	'89-'93		1	1.50	1.50	0.0200	
	TYWH057 RA	PANEL WHEEL HOUSE HILUX '89-'93	HILUX PICK UP 2WD	'89-'93		1	1.50	1.50	0.0200	
16	TYHL057 LA	HOOD LEDGE '93-'95	MIGHTY X	'89-'93	53702-89272	1	2.88	2.88	0.0400	
	TYHL057 RA	HOOD LEDGE '93-'95	MIGHTY X	'89-'93	53701-89220	1	2.88	2.88	0.0400	
17	TYR057 NA	RADIATOR SUPPORT '89-'93	YN100	'89-'93	53200-35020	1	6.00	7.00	0.0400	
18	TYRF057 NA	RADIATOR FAN SHROUD MIGHTY-X '93-'95	HILUX YN100	'93-'94	16261-54040	1	0.40	0.40	0.0020	

